




Part #: VFT-1000-UV-40  
 Date: May 17, 2011  
 Assembly #: VFT-AG051111-4  
 Connector 1 #: QSMA  
 Connector 2 #: QSMA  
 Flange type: NW 40 KF  
 Leak Detection 5 x 10<sup>-10</sup> cc/s He

[www.OceanOptics.com](http://www.OceanOptics.com)  
 Phone:727-733-2447  
 Fax:727-733-3962  
[Info@OceanOptics.com](mailto:Info@OceanOptics.com)  
 830 Douglas Ave.  
 Dunedin, FL 34698

\*Ask about our custom line of Optical Probes and Assemblies.\*

Fiber Type: UV-VIS  
 Fiber Core Diameter: 1000um

Epoxy Used: Epotek 353  
 Seal: glass to metal seal



Inspected by: *Van Foster*  
 Inspected by: *Van Foster*

Inspection Checklist  
 Polish: X  
 Concentricity: X  
 Cap Placement: X  
 Labeling: X  
 Color Coding: X  
 Ferrule length: X

Your Fiber was tested for performance prior to shipment. Please check your Fiber for breakage upon receipt. Ocean Optics will replace under warranty any broken Fiber returned within three weeks after customer receipt.