
rendering settings

Submit Working gas Magnetic field Introduction Preionization Electric field

Set the pressure and type of the working gas from which the plasma is formed. Pressure must be high enough for plasma to form, but low enough for gas breakdown to occur.




Gas type and pressure pWG= 16 mPa

Helium Hydrogen Next Set recommended value 3D model rendering method:

Static image (fast)

Interactive X3DOM (slower)



3D model rendering

engineering scheme

sliders and checkboxes

workflow buttons